

October 5, 2023

Aisha Moyla  
Assistant Vice President  
Campus Planning and Facilities  
PACE University  
One Pace Plaza  
New York, NY 10038

**RE: 161 William Street, New York, NY 10038  
Structural Stability**

Dear Ms. Moyla,

We visited 161 William on October 4, 2023, to review the building conditions. Our observations did not indicate any signs of structural damage, and no crack movement was recorded for the cracks along exposure 3 (wall adjacent to 57 Ann) since April 2023. Additionally, we have reviewed the vibration monitoring data available for 161 William Street. The vibration monitoring data does not indicate vibration levels that would've caused damage to the building. It is our opinion that 161 William is structurally stable, and no hazardous conditions are present.

Very truly yours,

**Thornton Tomasetti, Inc.**



Elisabeth A. Malsch, Ph.D., P.E.  
Managing Principal