

September 28, 2023

Aisha Moyla
Assistant Vice President
Campus Planning and Facilities
PACE University
One Pace Plaza
New York, NY 10038

**RE: 161 William Street, New York, NY 10038
Structural Stability**

Dear Ms. Moyla,

We have reviewed the vibration monitoring data available for 161 William Street. The vibration monitoring data does not indicate vibration levels that will cause damage to the building. It is our opinion that 161 William is structurally stable, and no hazardous conditions are present.

Very truly yours,

Thornton Tomasetti, Inc.



Elisabeth A. Malsch, Ph.D., P.E.
Managing Principal